

Overhaul of the machine housing



condition as delivered



Coated with electrically conductive paint



Applying of the noise reducer material





condition as delivered




Machine housing



Dismantling up to the last screw



All single parts are new painted



HF600 in the new condition

Overhaul the centrifuge bearing housing




condition as delivered



Crack detection by dye penetrant



Single parts






New cabinets in stainless steel



Control cabinet




Control with failsafe PLC




New local operation EX panel




New inertisation system




Start window




Process schematic of the centrifuge




Process schematic of the PAC-System



Long-time recording of process data



User Management



Input window for the process data